Maintenance

Battery Replacement

When the low battery symbol appears on the LCD, replace the meter's four 1.5V AA batteries.

Remove the rear battery compartment screw and open the battery compartment.

 Replace the batteries observing correct polarity, and replace the compartment cover and rear screw.

Warranty

EXTECH INSTRUMENTS CORPORATION warrants this instrument to be free of defects in parts and workmanship for one year from date of shipment (a six month limited warranty applies on sensors and cables). If it should become necessary to return the instrument for service during or beyond the warranty period, contact the Customer Service Department at (781) 890-7440 ext. 210 for authorization or visit our website at www.extech.com (click on 'Contact Extech' and go to 'Service Department' to request an RA number). A Return Authorization (RA) number must be issued before any product is returned to Extech. The sender is responsible for shipping charges, freight, insurance and proper packaging to prevent damage in transit. This warrenty does not apply to defects resulting from action of the user such as misuse, improper wiring, operation outside of specification, improper maintenance or repair, or unauthorized modification. Extech specifically disclaims any implied warranties or merchantability or fitness for a specific purpose and will not be liable for any direct, indirect, incidental or consequential damages. Extech's total liability is limited to repair or replacement of the product. The warranty set forth above is inclusive and no other warranty, whether written or oral, is expressed or implied.

Calibration and Repair Services

Extech offers repair and calibration services for the products we sell. Extech also provides NIST certification for most products. Call the Customer Service Department for information on calibration services available for this product. Extech recommends that annual calibrations be performed to verify meter performance and accuracy.



Support Hotline (781) 890-7440

Tech support: Ext. 200: Email: support@extech.com Repair/Returns: Ext. 210; Email: repair@extech.com Website: www.extech.com


Copyright © 2004 Extech Instruments Corporation

All rights reserved including the right of reproduction in whole or in part in any form.

User's Manual



Photo Tachometer / Counter



Introduction

Congratulations on your purchase of Extech's 461501 Photo Tachometer / Elapsed Timer-Counter. This device measures rotational speed (non-contact measurement) or linear speed (contact measurement) using the optional mechanical adapter. This meter offers an RS-232 Interface for PC connection, MIN/MAX/AVG readings, Data Hold, Counter, Elapsed Timer, Digital IN/OUT, and Auto Power OFF. Proper use and care of this meter will yield years of reliable service.

Safety

Ensure that the four AA 1.5V batteries are inserted correctly in the rear battery compartment (secured with one Phillips head screw):

Remove the batteries from the meter if the meter is to be stored for long periods.

Always keep fingers, articles of clothing, etc. from coming into contact with moving fans, blades, belts, etc. when testing.

Do not look directly at the light beam or point the beam toward anyone's eyes.

Specifications

	Range	Resolution	Accuracy
Non-Contact Spee	d Measurements		
RPM	10.00 - 99999	0.01 / 0.1 / 1	±(0.1% rdg ±2d)
Hz (rotations per sec)	0.200 - 2000.0	0.001 / 0.01 / .1	
Contact Speed Me	asurements		
RPM	20.00 - 29999	0.01/0.1/1	±(0.1% rdg ±2d)
M/min	1.000 - 2999.9	0.001 / 0.01 / .1	±(1% rdg ±2d)
Ft/min	3.00 - 10000	0.01/0.1/1	
Yard/min	1.00 - 3000		
	T Brown	May inn	ut frequency
	Range	Max. input frequency	
Counter	0 - 99999	10kHz with 5% duty cycle	

Dual 5-digit (99999 count) multifunction LCD Display

0.7 seconds (for 60 RPM) Display update rate

4MHz Oscillator (quartz crystal) Time base

2 to 11.8" (50 to 300mm) Measuring distance

Four 1.5V AA Batteries Power supply

35mA Power consumption

Automatic ranging Range selection

After 30 minutes (can be deactivated) Auto Power OFF


32 to 122F (0°C to 50°C) Operating temperature

6.8 x 2.5 x 1.5" (172 x 63 x 36mm) **Dimensions**

6.7 oz. (190g) Weight

Meter Description

- Photo light source and lens
- Multifunction LCD dual display
 - * Upper display: Elapsed Timer
 - * Lower display: Measurement/Counter
- START key: Power, Measure, Data Hold
- UNITS key and Auto OFF defeat key
- MIN / MAX / AVG key



Note: The tripod mount and battery compartment are located on the rear of the meter. The RS-232 DB-9 PC Interface port is located on the bottom of the meter.

Display Symbols and Units of Measure

Maximum reading display Max Min Minimum reading display Average reading display Ave

RPM Revolutions per minute in Non-Contact measurement mode RPM /

Revolutions per minute in Contact measurement mode

NOTE: Contact measurements can only be made with the optional mechanical adapter

Ft/min Feet per minute (for contact measurements only) Meters per minute (for contact measurements only) M/min Yards per minute (for contact measurements only) Yd/min

R/S Rotations per second (Hz)

(Number of Counts) Counter Function No.

tiege

H Display HOLD active < Photo Light Beam is ON

Replace battery

2/04

Operating Instructions

Preparing and affixing reflective tape

- Cut off a small piece of the supplied reflective tape. The optimal size is 1.0 x ½ cm or
- On the device under test, clean the area where the reflective tape is to be affixed. Ensure that no oil or other material, which could hinder the adhesiveness or reflectivity of the tape, is present.
- Affix tape to the clean area of the device under test. Make sure that the tape is placed as close to the outer edge of the object under test as possible.

Non-Contact Photo Tachometer Measurements

- 1. Press the START key to power the Tachometer.
- Press START again to activate the Photo light beam. Point the Photo light beam toward the object under test. The reflecting surface must be perpendicular to the light beam source. The optimum distance from light source to object under test is 2 to 12 in. (50 to 300mm), See Fig. 1.
- Read the RPM measurement data on the lower line of the LCD and the Elapsed Time on the upper LCD line.
- Note that if only minutes are displayed on the Elapsed Timer, the tachometer is in the Auto Power OFF mode (meter powers down after 30 mins, of non-use). To disable Auto Power OFF refer to the Section "Auto Power Shut OFF". If the Elapsed Timer shows hours and minutes, then the Auto Power OFF feature has been disabled.
- For rotational speeds less than 60 RPM, 1 to 6 seconds is required for the reading to stabilize (60 RPM = 1 second; 10 RPM = 6 seconds).
- For DATA HOLD, press the START key while measuring. The data display will freeze and the 'H' icon will appear on the LCD to alert the user that DATA HOLD is activated. Press the START key again to resume measurement.
- 7. To power the meter down, press and hold the START key until the LCD reads OFF and then goes blank.

Fig.1 - Non-Contact Measurements



Contact Measurements using optional Mechanical Adapter

- 1. Select the appropriate rubber head to suit the application at hand. To affix the rubber head you must insert it partially into the adapter and then, while turning it as if it were a knob, push the rubber head into the adapter.
- 2. Affix the mechanical adapter over the tachometer sensor and snap it firmly in place
- Press the START key to power the Tachometer.
- Press the Units key (at left) to select "RPM /", ft/min, m/min, vards/min, or r/s (rotations per second or Hz). Note that for contact RPM measurements use the "RPM/" instead of the "RPM" unit (the forward slash after RPM indicates that the reading is a contact measurement rather than a non-contact measurement)
- 5. Press START again to start measurement. Press the rubber head against the device under test (moving belt, escalator, etc.). Do not press too firmly against moving device. See Fig.2 below.
- 6. Read the measurement on the lower LCD line. The Elapsed Time appears on the upper LCD line. Do not exceed 29999 RPM with the mechanical adapter.
- 7. For DATA HOLD, press the START key again (while measuring). The data display will freeze and the 'H' icon will appear on the LCD to alert the user that DATA HOLD is activated. Press the START key again to resume measurement.
- To power the meter down, press and hold the START key until the LCD reads OFF and then goes blank. Auto Power Off will power the meter down after 30 mins, of nonuse. To defeat Auto Power Off refer to section "Auto Power Shut OFF".

Fig. 2 - Contact Measurement examples



Slow Speed Measurement Considerations

If the speed of a rotating object is slow, the use of a tripod is highly recommended. A tripod will hold the meter in place with minimum movement providing more accurate readings. Also, use additional pieces of reflective tape if possible.

If multiple pieces of tape are used, each piece of tape should be placed equidistant. Any number of pieces can be used but you must divide the reading by the number of pieces to obtain the correct result. Use this equation:

Correct RPM = Reading / No. of tape pieces.

In the example for Fig. 3, four pieces of tape are used. If the meter reading is 12 RPM, the equation becomes: RPM = 12 / 4; therefore the Correct RPM is 3.

Fig. 3 - Rotating device with 4 pieces of reflective tape

2/04

Maximum, Maximum, and Average Readings

This feature permits the user to analyze the stability of a device under test with regard to rotational speed. This is achieved by comparing maximum, minimum, and average readings. over time.

- To display the Max, Min, and Avg readings while measuring, first press the Function key (located above and to the right of the START key). The MAX display icon will appear on the left side of the LCD along with the reading which indicates the highest reading since measurement began.
- Press the Function key again and the MIN indicator along with the lowest reading will display.
- 3. Press the Function key again and the Average reading will display. The average function is a True Average (refer to equation below). If the summation of average values overflows (n=65535) then the last average RPM will be used as an initial value for successive calculations (n will be reset to 1).

$$RPM_{aw} = \frac{1}{n} \sum (rpm)_n; \sum (rpm) < 2^{32}; n < 65535$$

- When the START key is pressed, the Max/Min/Ave values begin to be calculated and recorded. Users can then press the Function key (at right) to review the stored values.
- To exit this mode, press and hold the Function key for approx. 3 seconds until the MAX, MIN, and AVE indicators disappear. When this mode is exited, the stored data is reset (cleared).


Data Hold

Press the START key while measuring to freeze the display. The "H" icon will appear on the LCD to indicate that the Data Hold mode is activated. Press the START key again to exit the Data Hold mode and return to normal operation

Counter Function

This meter permits the counting of objects as they pass through its light beam (on a conveyor belt, for example). As shown in the diagram below, the Photo tachometer sends out a beam of light that is reflected back. Each time a product breaks the beam another count takes place and the display is updated. In addition, the top line displays elapsed time. The user must tripod-mount the meter and also provide a reflective surface as shown in Fig.4 below.

Fig. 4 - Product Counting



Press the Unit key (at left) repeatedly until "No." appears on the left side of the LCD. The Counter display (lower, main LCD line) will be set to zero. Press START key again to begin counting pulses. Each object that breaks the light beam will be counted (in this mode Auto Power OFF is disabled). To pause counting (DATA HOLD), press the START key once, to resume counting press START again. To reset the Counter (zero), press the Function key (right). Elapsed Time is shown on the top line of the display in HR:MN format. Note that when the counter is reset, the Elapsed Timer does not return to zero. To reset the Elapsed Timer the meter power has to be cycled.

Counting with the Digital Input Feature

This tachometer accepts a DC voltage input through its RS-232 port (pin 8 for signal input with pin 5 as signal ground). A HIGH input is in the range of 4.5V and a LOW input is in the range of OV. Each input pulse sensed by the tachometer is counted and the display is updated. Cover the light beam lens while using the Digital Input feature to avoid display errors. To set up the tachometer as a counter, follow the instructions above in the section entitled "Counter Function".

Digital Output Feature

This tachometer outputs a square wave from its RS-232 port (pin 8 and pin 5 as signal ground) to an oscilloscope or other device. The 5V digital pulse (square wave) changes frequency proportionately to the measured RPM.

Auto Power Shut Off

This Tachometer is equipped with an Automatic Power OFF feature. After approx. 30 minutes. If no keys are pressed, the meter shuts down. This helps to conserve battery life.

To defeat this feature press and hold the Units key (at left) with meter powered until both the hours and minutes fields are displayed on the Elapsed Timer LCD line (top) instead of only the minutes field.

When only the minutes field is displayed on the Elapsed Timer, the Auto Power OFF feature is activated. When both the hours and minutes fields are displayed on the Elapsed Timer, the Auto Power OFF feature is defeated.

2/04

PC Interface via RS-232 Port

Communications Protocol

Ten bytes are output through the DB-9 RS-232 port (located on meter bottom). The protocol is presented below:

Byte 1: Leading byte 0x0D Byte2: Decimal point (LCD)

bit0: dp1 (0000.0) bit1: dp2 (000.00)

bit2: dp3 (00.000)

Byte3: Status Flags

bit0: low battery

bit1: Maximum reading feature over range

bit2: Counter over range

bit3: Auto power off disabled bit4: Minimum reading feature over range

bit5: Average reading feature over range

Byte4: Units

bito: RPM

bit1: m/min bit2: ft/min

bit3: yr/min

bit4:rps

bit5: not used

bit6: counter mode

Byte5: Function

bit0: Normal mode of operation

bit1: Maximum reading mode

bit2: Minimum reading mode bit3: Average reading mode

Byte6: Overload and Data Hold Status Flags

bit4: LCD reading overload (OL)

bit7: Data Hold Mode

Byte7: Least significant byte of reading (binary format)

Byte8: 2nd byte of reading (binary) Byte9: 3rd byte of reading (binary)

Byte10: Most significant byte of reading (binary)

Hardware Connection

The tachometer's RS-232 DB-9 serial communications port is located on the meter bottom. Use the supplied cable to connect the meter's port to the PC serial COM port. A 25- to 9-pin adapter is included in the event that the PC in question has a 25-pin COM port only.

Windows[™] Tachometer Software Installation

For Windows 1th 95/98

Start Windows™ 95/98

Insert Program Disk in Floppy Drive

Press START key and then select RUN

Type a:\setup (or b:\setup) and press ENTER

Main Software Window

When the tachometer software is executed, the program checks for a connected tachometer or for an available serial COM port. If no serial port is available or if the meter is not connected correctly, the message "NO COM" is displayed on the lower right hand side of the Main Software Window (shown below).




Fig. 5 - Main Software Window

Sugar

1,71

2/04

8

Main Software Window Fields

Sample: Sample rate (interval of time between recorded readings). The

> Sample rate is user-selectable from 1 to 32,767 seconds. Double click on this field or select Sample Rate from the

OPTION menu to select sample rate.

Option: The operational mode of the tachometer (Normal, Max, Min, or

Avg)

Units: Units of measure (RPM, RPM/, m/min/ ft/min, yd/min, R/S (Hz),

and No. (counter)). The units can only be selected from the

meter front panel using the Units key (key on left).

Value: Tachometer's measurement reading Range: Tachometer measurement range

Minimum: The lowest reading recorded Maximum: The highest reading recorded

Reset: Clear Minimum and Maximum reading. Press RESET to clear.

Lower: User selectable Low Alarm (Window flashes UNDER if

measurement falls below this user-defined limit).

Upper: User selectable High Alarm (Window flashes OVER if

measurement rises above this user-defined limit).

Main Software Window Menu Items

FILE

Name: User selected data file name

Start Recording: Select to begin recording data to file

End Recording: Select to cease data recording.

View File: Open the data file for viewing and printing. See List illustration in Fig. 6 below. The FILE heading in the VIEW FILE window permits the user to check the

number of data blocks, records, or characters read

Print Data: Prints stored measurement data.

Exit: Closes the datalogging program.

DISPLAY

Refer to Fig. 6 below for the four display types. You can open each display type using the DISPLAY menu from the Main Software Window or you can use the following keyboard shortcuts.

Keyboard shortcuts

CTRL+D: Opens Digital Display


CTRL+A: Opens Analog Display

CTRL+L: Opens List Display

CTRL+G: Opens Graph Display

Fig. 6 - Display Types

Analog Display Mode




Digital Display Mode



List Display Mode

Graph Display Mode





in the main Sonware vymuow, the rollowing lients

SAMPLE RATE

Enter the rate at which data is recorded.

UPPER LIMIT:

Enter a high measurement limit. If this limit is exceeded the

OVER message will appear in the software window.

LOWER LIMIT:

Enter a low measurement limit. If this limit is exceeded the

UNDER message will appear on the software window.

GRAPHIC MODE: Select the way you desire the graph to display (Dots or bars)

BAUD RATE

9600 bps (fixed).

NOTE: There are two menu items in Graph Mode:

a. PRINT: Allows the user to print the graph.

b. SCALE: Permits the user to select the Min/Max units for the Y axis